

How to fill the refillable cartridge compatible with Brother LC51


Take the rubber cover out



Take the syringe with ink to fill the cartridge (if you do not have the syringe, please call our sales department to order one).

The syringe has to have the amount of ink that you need to fill into the cartridge. E.g. if your cartridge is empty, get 25 ml of ink for black color and 13 ml of ink for the color cartridge.


Insert the syringe without needle in the hole.



Pump the air of the cartridge by sliding the top up. Move it up until you complete the capacity of the cartridge.



Release the top and wait for few second. The cartridge will get the ink.



After that put the cover in again.



© Macro Enter Corp.